COAL AGE

With Which is Consolidated The Colliery Engineer

INDEX TO VOLUME XXIV

July 1 to December 31, 1923

Make Threetend entirely and denoted by an	Page	
Note.—Illustrated articles are denoted by an asterisk (*), book notice by a dagger (†).	Anthracite	Page Blizzard trial189, 342, 384, 799, 835, 943
Titles are often abbreviated. They are indexed under their most important words, or, if no	—Conference83, 115 187, *293, *332, 335, 371, (e) 385	Bloomfield's Labor Digest 128
word be distinctive, under the first one (except "A," "The," etc.) or under some topical word		Boiler, banking fire under 966
"A," "The," etc.) or under some topical word not found in the title. (e) denotes editorials.	—Dispute (e)	Boiler room, Lynch
Following is a list of the pages included in	—Economy show	Boiler practice, Advance in steam. Price. •767 Boilers, pulverized fuel for
the several numbers of the volume by date:	Miners' demands	Bollers, water supply. Navaio mine 390
July 5	-Production costs (e)	Bolt, M
" 12	—Profits report Coal Comm	Bonding, efficient method of cross
" 26	-Report Coal Comm 43, 116, 151, (e)	Bonding, importance of
Aug. 2	—Report Coal Comm43, 116, 151, (e) 41, 42, 127. Press comments 82 —Shipments123, 304, 500, 650, 798, 943	Bookkeeping, Machine at mine McNell •319
" 16	—Shortage, causes 58	Book reviews 432, 856 Boom, Knox Gon-Box Loading 174
" 30 307-344	—Sizes	Branch Coal & Coke Co. Locomotive taken
Sept 6 345-384	-Strike., 371, 373, 374, 415. Agreement, 458	up mountainside*105
13	—Substitute	Brass, drilling, Radebaugh
" 27	Apprentice system in mining 151	up mountainside 1105 Brass, drilling, Radebaugh 669 Brazing, Welding and Radebaugh 999 Breaker, fire protection, Hammond 729 Brennan, W. 115 Brevity (e) 92 Brick Carbofers 92
Oct. 4	Arbitration (e)	Brennan, W
" 18 579-616	Arbitration (e)	Drick, Carbonax
Nov. 1	Arc, calculating	Bright, G
. 8	Arresters, Testing lightning, Goodwin*210	Briquetting binder, seaweed for
	Ashes, flushing	Briquetting lignite, Brenfait, Sask 501
" 22	Asia, production coal	Briquets Indo-China •208 Briquets Russia •512
Dec. 6	Associated Coal Bureau of Kansas City. 67 Assn. Bituminous Operators Central Pa. 616	British Empire Steel Corp.—Coal produc-
" ·20 909-944	Association, electrical engineers, national	Brotherhood Locomotive Engineers 80
" 27 945-976	(e)	Brushes for mine locomotives 633
10 to	—Meeting 604	Brydon, J. C
A	—Program 446	of Mines
	Associations, trade (e)	Budget, U. S. Gov't. 975 Building mining towns. Downing. 63
Abandoned mines, Entering. Discussion. 519	Australia, production, coal 330 Austria	Bulgaria, production coal 330 Bulletin board at mines 285
Accidents	—Coal reserves	
—Causes classified	—Production coal and lignite	Buntons easy. Shaft designed to make re-
—Distribution by occupation	Axie conar	placement
Reducting 149 Accounting sales, at mine. McNeil		BUREAU OF MINES
Accounting, sales, at mine. McNeil319 Aerial tramway. Traber and Richards		-Concentric all-rubber covered cables.
Africa, production coal	Bache-Denman Coal Syndicate vs. U. M. W. 675 Bankers' acceptances	Illsley and Freeman 280
Air, compressed, Ventilating by. Discussion, 598 Air dome prevents breaking of column line. •437	Rarnes J H 334	—Davy safety lamp. Paul and Hooker 134 —Engineers to make safety reports 10
Air, humidification mine	Bathhouse Gallun-American Coal Co *428	-Explosives, sales, U. S
		Hatalitian II C 00 000 000 FOF MEO 050
Air, moistening, in intake, Chester*663		—Explosives, sales, U. S
Air, Resistance to flow (inq.) 561. Dis-	Bearings. How to babbitt motor 252	-Spontaneous combustion Pa. coals 16
cussion*821 Airways in Mines, Multiplying. Discus-	Bearings, How to babbitt motor. 252 Bearings, roller, self-aligning. 245 Bearings, roller vs. plain. 595	— Spontaneous combustion Pa. coals 16 — Testing anthracite from New England
Air Resistance to flow (inq.) 561. Dis- cussion	Bearings, How to babbitt motor. 252 Bearings, roller, self-aligning. 245 Bearings, roller vs. plain. 595 Beautify a coal mine? (e). 618	- Report, annual Solution Pa. coals 16 - Spontaneous combustion Pa. coals 16 - Testing anthracite from New England yards 115 Burns Bros 25
Air Resistance to flow (inq.) 561. Discussion	Bearings, How to babbitt motor. 252 Bearings, roller, self-aligning. 245 Bearings, roller vs. plain. 595 Beautify a coal mine? (e). 618 Beaver Valley Coal Co. 798	- Report, annual - Spontaneous combustion Pa. coals. 16 - Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e). 690
Air Resistance to flow (inq.) 561. Dis- cussion	Bearings How to babbitt motor 252	- Report, annual Solution Pa. coals 16 - Spontaneous combustion Pa. coals 16 - Testing anthracite from New England yards 115 Burns Bros 25
Air. Resistance to flow (inq.) 561. Dis- cussion Section Section	Bearings How to babbit motor 252	- Report, annual - Spontaneous combustion Pa. coals. 16 - Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e). 690
Air. Resistance to flow (inq.) 561. Discussion	Bearings How to babbitt motor 252	- Report, annual - Soa - Sopontaneous combustion Pa. coals 16 - Testing anthracite from New England yards 115 Burns Bros 25 Business indicators and coal stocks (e) 690 Business statistics (e) 690
Air, Resistance to flow (inq.) 561. Discussion Airways in Mines, Multiplying Discussion Airways, resistance due to bends (inq.). Holman Alabama —Appropriation mining dept. —Coal land leased Gov't —Production —Railroad from Kimbrough —Hailroad from Kimbrough —Inion 821 822 823 824 825 826 827 827 828 829 820 821 821 822 823 826 826 827 828 829 820 820 821 821 822 823 826 826 827 828 828 829 820 820 820 820 820	Bearings How to babbitt motor 252	- Report, annual - Sota - Sopontaneous combustion Pa. coals 16 - Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business statistics (e) C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931
Air Resistance to flow (inq.) 561. Discussion Airways in Mines, Multiplying Discussion Airways, resistance due to bends (inq.). Holman Alabama —Appropriation mining dept. —Coal land leased Gov't —Production —Railroad from Kimbrough —Union Alabama Min. Inst 826	Bearings How to babbitt motor 252	- Report, annual - Sota - Sopontaneous combustion Pa. coals 16 - Testing anthracite from New England yards 115 Burns Bros 25 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cable, spring reel for 592
Air. Resistance to flow (inq.) 561. Discussion	Bearings How to babbitt motor 252	- Report, annual - Sotal - Sopontaneous combustion Pa. coals. 16 - Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cables pring reel for 592 Cables Concentric all-rubber covered:
Air. Resistance to flow (inq.) 561. Discussion Airways in Mines, Multiplying. Discussion Airways, resistance due to bends (inq.) Holman Alabama —Appropriation mining dept. 575 —Coal land leased Gov't 231, 382 —Production 158 —Railroad from Kimbrough 941 —Union 162 Alabama Min. Inst. 826 Alaska —Coal marketed 88 —Bituminous Coal Co. 195 —Black powder discontinued 335	Bearings How to babbitt motor 252	- Report, annual - Sophia - So
Air. Resistance to flow (inq.) 561. Discussion	Bearings How to babbitt motor 252	- Report, annual - Solution - Sol
Air. Resistance to flow (inq.) 501. Discussion Airways in Mines, Multiplying Discussion Airways, resistance due to bends (inq.) Holman	Bearings	Report, annual Spontaneous combustion Pa. coals 16 Spontaneous combustion Pa. coals 16 Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cables, pring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 800 Cables, Concentric Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92
Air. Resistance to flow (inq.) 501. Discussion	Bearings How to babbitt motor 252	Report, annual Spontaneous combustion Pa. coals 16 Spontaneous combustion Pa. coals 16 Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Brankless statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cable. Spring reel for 592 Cables, Concentric all-rubber covered 11 11 11 11 11 11 11 11 11 11 11 11 11
Air. Resistance to flow (inq.) 501. Discussion	Bearings	Report, annual Spontaneous combustion Pa. coals 16 Spontaneous combustion Pa. coals 16 Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Brankless statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cable. Spring reel for 592 Cables, Concentric all-rubber covered 11 11 11 11 11 11 11 11 11 11 11 11 11
Air. Resistance to flow (inq.) 501. Discussion	Bearings	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cabinet, Big three of 515 Cable, Splicing 3-conductor 931 Cable, spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow 965 Caisson method sinking shaft, Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. — Franklin byproduct plant, Richardson, 309 —Rosedale coke ovens, Richardson, 93, 201 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch, 627
Air, Resistance to flow (inq.) 561. Discussion	Bearings	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cabinet, Big three of 515 Cable, Splicing 3-conductor 931 Cable, spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow 965 Caisson method sinking shaft, Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. — Franklin byproduct plant, Richardson, 309 —Rosedale coke ovens, Richardson, 93, 201 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch, 627
Air. Resistance to flow (inq.) 501. Discussion 1821 Airways in Mines, Multiplying Discussion 1821 Airways, resistance due to bends (inq.) 1821 Holman 111 Alabama 111 Alabama 111 Alabama 111 Alabama 111 - Coal land leased Gov't 231, 382 - Production 158 - Railroad from Kimbrough 941 - Union 162 Alabama Min. Inst, 826 Alaska Coal marketed 88 - Bituminous Coal Co 195 - Black powder discontinued 336 - Black powder discontinued 348 Allegheny-Pittsburgh Coal Co Safety block, Brosky 78 Alibi, It's a thin (e) 425 Almer, Federation of Labor—Convention 607 Amer, Fuel Co.—Strike Beltona mines 88 Amer, Inst. Chemical Engrs 642	Bearings	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cabinet. Big three of 515 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow 985 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co.—Franklin byproduct plant. Richardson. 309 — Rosedale coke ovens. Richardson. 93, 201 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper 354
Air. Resistance to flow (inq.) 561. Discussions 182. Airways in Mines, Multiplying. Discussion 182. Airways, resistance due to bends (inq.) 182. Airways, resistance due to bends (inq.) 182. Alabama — Appropriation mining dept. 575. —Coal land leased Gov't. 231, 382. —Production 158. —Railroad from Kimbrough 941. —Union 162. Alaska — Coal marketed 88. —Coal marketed 88. —Bituminous Coal Co. 195. —Black powder discontinued 335. Allegheny-Pittsburgh Coal Co.—Safety block. Brosky 192. Allegheny-Pittsburgh Coal Co.—Safety 193. Aluminum Ore Co. flooding of Radium 193. America, coal reserves 12. Amer. Federation of Labor—Convention. 607. Amer. Fuel Co.—Strike Beltona mines 88. Amer. Inst. Chemical Engrs. 642. Amer. Inst. Chemical Engrs. 642.	Bearings	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Concentric all-rubber covered. 189 Cables, Concentric all-rubber 27 Calculating washed coal and refuse 170 Calculating washed coal and refuse 170 Calder Ex-Senator W M 92 Cambria Steel Co, Franklin byproduct plant, Richardson 93, 201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper 354 CANADA —Briquets from Alberta coal 343
Air. Resistance to flow (inq.) 561. Discussions (inq.) Airways in Mines, Multiplying. Discussion	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Suspending feeder, Beddow. 965 Caisson method sinking shaft, Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. —Franklin byproduct plant, Richardson. *309 —Rosedale coke ovens. Richardson. *309 —Rosedale roke ovens. Richardson.
Air. Resistance to flow (inq.) 501. Discussion	Bearings	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Concentric all-rubber covered. 180 Cables, Suspending feeder. Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. —Franklin byproduct plant, Richardson. 930 — Rosedale coke ovens. Richardson. 93, 201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch. 627 — Paper 354 CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 Express coal. 28, 89, 384, 577, 764, 975
Air. Resistance to flow (inq.) 501. Discussion	Bearings	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables, Splicing 3-conductor 931 Cable, spring reel for 592 Cables, Concentric all-rubber covered. 11 Illsley and Freeman 280 Cables, Concentric all-rubber covered. 11 Illsley and Freeman Beddow 985 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder Ex-Senator W M 92 Cambria Steel Co. —Franklin byproduct plant. Richardson 309 —Rosedale coke ovens. Richardson 93, 201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper 354 CANADA —Briquets from Alberta coal 343 —Crow's Nest Pass mines 116 —Exports, coal 28, 89, 384, 577, 764 —Freight rates 270 —Freight rates 366 —Fuel controllers, local 486 —Fuel controllers, local 486 —Fuel col tax 836
Air. Resistance to flow (inq.) 501. Discussion	Bearings How to babbitt motor 252	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow 985 Caisson method sinking shaft, Brosky 9273 Calculating washed coal and refuse 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant, Richardson 93 —Rosedale coke ovens, Richardson 93, 201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper 354 CANADA —Briquets from Alberta coal 343 —Crow's Nest Pass mines 116 —Exports, coal 28, 89, 384, 577, 764 —Freight rates 270 —Fuel ontrollers, local 406 —Fuel oil tax 89, 197, 270, 384, 577, 764
Air. Resistance to flow (inq.) 501. Discussion	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cables, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Concentric all-rubber covered. Cables, Suspending feeder. Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. —Franklin byproduct plant. Richardson. *309 —Rosedale coke ovens. Richardson. *93, *201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch. 627 —Paper 354 CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal. 28, 89, 384, 577, 764 —Freight rates . 270 —Freight rates . 270 —Freight rates . 270 —Freight rates . 283 —Imports, coal. 89, 197, 270, 384, 577, 764 —Lignite . 330, 537
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion is in Mines, Multiplying. Discussion is in Mines, Multiplying. Discussion in Mines, Multiplying in Mines, M	Bearings How to babbitt motor 252	— Report, annual—Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Suspending feeder, Beddow 665 Caisson method sinking shaft, Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co,—Franklin byproduct plant, Richardson 93, 201 Canadian Inst. Min. & Metall. —Convention So, Saskatchewan branch 627 —Paper 354 CANADA —Briquets from Alberta coal 343 —Crow's Nest Pass mines. 16 —Exports, coal 28, 89, 384, 577, 764 —Freight rates 770 —Freight rates 98, 197, 270, 384, 577, 764 —Imports, coal 89, 197, 270, 384, 577, 764
Air. Resistance to flow (inq.) 501. Discussions. Airways in Mines, Multiplying. Discussion Airways, resistance due to bends (inq.). Holman Appropriation mining dept. 575 —Coal land leased Gov't. 231, 382 —Production 158 —Railroad from Kimbrough 941 —Union 162 Alabama Min. Inst. 826 Allegheny-Pittsburgh Coal Co.—Safety block. Brosky 978 Alibi, It's a thin (e) 425 Aluminum Ore Co. flooding of Radium mine 892, 942 Amer. Inst. Chemical Engrs. 642 Amer. Inst. Chemical Engrs. 642 Amer. Inst. Chemical Engrs. 642 Amer. Inst. Chemical Engrs. 764 Amer. Inst. Min. & Metall. Engrs. 962 —Weeting, annual 764 Amer. Inst. Min. & Metall. Engrs. 963 —Weeting annual 764 Amer. Min. Congress 481, 627, 885 —Blasting (e) 533 —Exhibits 596, 658 —Teture (e) 563 —Meeting 488, \$523, \$533	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cables splicing 3-conductor 931 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, Concentric all-rubber covered. Illsley and Freeman 180 Cables, Suspending feeder. Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. —Franklin byproduct plant. Richardson. *309 —Rosedale coke ovens. Richardson. *93, *201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch. 627 —Paper 354 CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal. 28, 89, 384, 577, 764 —Freight rates 270 —Fuel controllers, local 466 —Fuel oil tax 836 —Fuel oil tax 836 —Imports, coal. 89, 197, 270, 384, 577, 764 —Lignite 330, 537 —MgDougall, D. H., resigns. 330, 537 —MgDougall, D. H., resigns. 581
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion is Mines, Multiplying. Discussion is Mines, Multiplying. Discussion is Mines, February is Multiplying. Discussion is Mines in Multiplying. Discussion in Multiplying. Discussi	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring real for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper 354 CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 — Exports, coal. 28, 89, 384, 577, 764 — Freight rates 270 — Fuel controllers, local. 486 — Fuel oil tax 368 — Imports, coal. 89, 197, 270, 384, 577, 764 — Lignite 330, 537 — McLachlan, J. B. 687, 725 — McDougall, D. H., resigns. 330, 537 — Magazine explodes Gibson colliery. 281 — Mexico coal. 9075
Air, Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion is in Mines, Multiplying. Discussion in Mines, Mi	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring real for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper 354 CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 — Exports, coal. 28, 89, 384, 577, 764 — Freight rates 270 — Fuel controllers, local. 486 — Fuel oil tax 368 — Imports, coal. 89, 197, 270, 384, 577, 764 — Lignite 330, 537 — McLachlan, J. B. 687, 725 — McDougall, D. H., resigns. 330, 537 — Magazine explodes Gibson colliery. 281 — Mexico coal. 9075
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion in Mines, Mi	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 C Cables, Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring real for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder, Beddow. 965 Caisson method sinking shaft. Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Rosedale coke ovens. Richardson. 93 — Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper 354 CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 — Exports, coal. 28, 89, 384, 577, 764 — Freight rates 270 — Fuel controllers, local. 486 — Fuel oil tax 368 — Imports, coal. 89, 197, 270, 384, 577, 764 — Lignite 330, 537 — McLachlan, J. B. 687, 725 — McDougall, D. H., resigns. 330, 537 — Magazine explodes Gibson colliery. 281 — Mexico coal. 9075
Air. Resistance to flow (inq.) 501. Discussion	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 9331 Cable, Splicing 3-conductor 9331 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder. Beddow 985 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calculating washed coal and refuse 170 Calcer, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant, Richardson 93, 201 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch 627 — Paper 354 CANADA — Briquets from Alberta coal 343 — Crow's Nest Pass mines 116 — Exports, coal 28, 89, 384, 577, 764 — Freight rates 270 — Fuel oil tax 89, 197, 270, 384, 577, 764 — Lignite 330, 537 — McLachlan, J. B 687, 725 — McDougall, D. H., resigns 330, 537 — Magazine explodes Gibson colliery 281 — Mexico coal 89, 197, 270, 384, 577, 615 — Number men employed 577 — Peace River — Production, coal 89, 125, 161, 197, 330, 343, 382, 727, 784, 720, 736, 875, 777, 615
Air. Resistance to flow (inq.) 501. Discussions. Airways in Mines, Multiplying. Discussion Airways, resistance due to bends (inq.). Holman Appropriation mining dept. 575 —Coal land leased Gov't. 231, 382 —Production 158 —Railroad from Kimbrough 941 —Union 162 Alasma Min. Inst. 826 Alaska —Coal marketed 88 —Bituminous Coal Co. 195 —Black powder discontinued 335 Allegheny-Pittsburgh Coal Co.—Safety block, Brosky 978 Allibi, It's a thin (e) 425 Aluminum Ore Co. flooding of Radium mine 892, 942 America, coal reserves 17 Amer. Federation of Labor—Convention. 607 Amer. Fruel Co.—Strike Beltona mines 88 Amer. Inst. Chemical Engrs. 642 Amer. Inst. Elec. Engrs. —Lehigh Valley section, meeting 886 —Meeting, annual 70 Amer. Inst. Min. & Metall. Engrs. 962 —Washington section 962 —Washington section 962 —Amer. Min. Congress 433 —Washington section 962 —Shibits 596, 658 —Etuture (e) 503 —Meeting 488, \$23, \$63 —Program 488, \$23, \$63 —Mer. R. Assn. 152, 466, 502 Amer. R. Assn. 152, 466, 502 Amer. R. Assn. 152, 466, 502 Amer. Wholesale Coal Assn.	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 9331 Cable, Splicing 3-conductor 9331 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder. Beddow 985 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calculating washed coal and refuse 170 Calcer, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant, Richardson 93, 201 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch 627 — Paper 354 CANADA — Briquets from Alberta coal 343 — Crow's Nest Pass mines 116 — Exports, coal 28, 89, 384, 577, 764 — Freight rates 270 — Fuel oil tax 89, 197, 270, 384, 577, 764 — Lignite 330, 537 — McLachlan, J. B 687, 725 — McDougall, D. H., resigns 330, 537 — Magazine explodes Gibson colliery 281 — Mexico coal 89, 197, 270, 384, 577, 615 — Number men employed 577 — Peace River — Production, coal 89, 125, 161, 197, 330, 343, 382, 727, 784, 720, 736, 875, 777, 615
Air, Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion is Mines, Mi	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 945 C Cabies Splicing 3-conductor 9331 Cable, Splicing 3-conductor 9331 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, uspending feeder, Beddow. 965 Caisson method sinking shaft, Brosky. 273 Calculating washed coal and refuse. 170 Calder, Ex-Senator W. M. 92 Cambria Steel Co. Franklin byproduct plant, Richardson. 93, 201 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch. 627 —Paper 354 CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal. 28, 89, 384, 577, 764 —Freight rates 270 —Free ontrollers, local. 466 —Fuel oil tax 89, 197, 270, 384, 577, 764 —Imports, coal. 89, 197, 270, 384, 577, 64 —Imports, coal. 89, 197, 270, 384, 577, 64 —McDougall, D. H., resigns. 337 —McLachlan, J. B. 687, 725 —McDougall, D. H., resigns. 387 —Magazine explodes Gibson colliery. 281 —Mexico coal. 89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 615, 725, 764, 799, 836, 871, 907 —Regulate sale coal. 81, 125, 424, 537 —Strikes 81, 152, 424, 537 —Strikes . 81, 152, 424, 537
Air. Resistance to flow (inq.) 501. Discussions in Mines, Multiplying. Discussion	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cables, pering reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder. Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 93 — Franklin byproduct plant. Richardson. 309 — Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 — Exports, coal. 28, 89 384, 577, 764 — Freight rates 270 — Freigh rates 270 — Fuel oil tax 836 — McLachlan. J. B. 687, 577 — McLachlan. J. B. 687, 577 — McDougall. D. H., resigns. 537 — McDougall. Sast physical split s
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion in Mines in Mines in Multiplying. Discussion in Mines in	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, uspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 81 —Franklin byproduct plant. Richardson. 309 —Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal 28, 89 384, 577, 764 —Freight rates 270 —Fuel controllers, local 466 —Fuel oil tax 836 —McLachlan J. B. 687, 270 —McDougall, D. H., resigns. 537 —Mexico coal 89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 616, 725, 764, 799, 836, 871, 907 —Rescue, mine, competition, Blairmore, 172 —Rescue, mine, competition, Blairmore —Tax foreign fuel oil
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion in Mines in Multiplying. Biscussion in Mines in	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, uspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 81 —Franklin byproduct plant. Richardson. 309 —Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal 28, 89 384, 577, 764 —Freight rates 270 —Fuel controllers, local 466 —Fuel oil tax 836 —McLachlan J. B. 687, 270 —McDougall, D. H., resigns. 537 —Mexico coal 89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 616, 725, 764, 799, 836, 871, 907 —Rescue, mine, competition, Blairmore, 172 —Rescue, mine, competition, Blairmore —Tax foreign fuel oil
Air. Resistance to flow (inq.) 501. Discussions. Airways in Mines, Multiplying. Discussion Airways, resistance due to bends (inq.). Holman Appropriation mining dept. 575 —Coal land leased Gov't. 231, 382 —Production 158 —Railroad from Kimbrough 941 —Union 162 Alasham Min. Inst. 826 Alasham Min. Inst. 826 Alasham Arketed 88 —Bituminous Coal Co. 195 —Black powder discontinued 335 Allegheny-Pittsburgh Coal Co. Safety block, Brosky 978 Alibi, It's a thin (e) 425 Aluminum Ore Co. flooding of Radium mine 892, 942 America, coal reserves 177 Amer. Federation of Labor—Convention. 607 Amer. Fruel Co.—Strike Beltona mines 88 Amer. Inst. Chemical Engrs. 642 Amerinst. Chemical Engrs. 642 Amerinst. Elec. Engrs. 964 —Meeting, annual 76 —Meeting 962 —Mering 488, \$523, \$638 —Program 488, \$523, \$638 —Program 488, \$23, \$638 —Program 488 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 539 —Program 489 —Standardization 596, 658, 782, 923, (e) 5	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, uspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 81 —Franklin byproduct plant. Richardson. 309 —Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal 28, 89 384, 577, 764 —Freight rates 270 —Fuel controllers, local 466 —Fuel oil tax 836 —McLachlan J. B. 687, 270 —McDougall, D. H., resigns. 537 —Mexico coal 89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 616, 725, 764, 799, 836, 871, 907 —Rescue, mine, competition, Blairmore, 172 —Rescue, mine, competition, Blairmore —Tax foreign fuel oil
Air. Resistance to flow (inq.) 501. Discussion in Mines, Multiplying. Discussion is Mines, Mi	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cables Splicing 3-conductor 931 Cable, Splicing 3-conductor 931 Cable, Spring reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, uspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder, Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 81 —Franklin byproduct plant. Richardson. 309 —Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. —Convention So. Saskatchewan branch 627 —Paper CANADA —Briquets from Alberta coal. 343 —Crow's Nest Pass mines. 116 —Exports, coal 28, 89 384, 577, 764 —Freight rates 270 —Fuel controllers, local 466 —Fuel oil tax 836 —McLachlan J. B. 687, 270 —McDougall, D. H., resigns. 537 —Mexico coal 89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 616, 725, 764, 799, 836, 871, 907 —Rescue, mine, competition, Blairmore, 172 —Rescue, mine, competition, Blairmore —Tax foreign fuel oil
Air. Resistance to flow (inq.) 501. Discussion	Bearings How to babbitt motor 252	— Spontaneous combustion Pa. coals. 16 — Testing anthracite from New England yards 115 Burns Bros. 25 Business indicators and coal stocks (e) 690 Business indicators and coal stocks (e) 690 Business statistics (e) 945 C Cabinet. Big three of 515 Cable. Splicing 3-conductor 931 Cables, pering reel for 592 Cables, Concentric all-rubber covered. Illsley and Freeman 280 Cables, suspending feeder. Beddow 965 Caisson method sinking shaft. Brosky 273 Calculating washed coal and refuse 170 Calder. Ex-Senator W M 92 Cambria Steel Co 92 Cambria Steel Co 93 — Franklin byproduct plant. Richardson. 309 — Rosedale coke ovens. Richardson. 93 Canadian Inst. Min. & Metall. — Convention So. Saskatchewan branch. 627 — Paper CANADA — Briquets from Alberta coal. 343 — Crow's Nest Pass mines. 116 — Exports, coal. 28, 89 384, 577, 764 — Freight rates 270 — Freigh rates 270 — Fuel oil tax 836 — McLachlan. J. B. 687, 577 — McLachlan. J. B. 687, 577 — McDougall. D. H., resigns. 537 — McDougall. Sast physical split s

Page	Page	Page
Carbide light nearly ignites gas. Wade. 861 Carbocite	Coal—Continued —Reserves, World	Deadlock broken (e)
Carbon dioxide fights Bitner mine fire. Jones	—Reserves. World 17 —Quality inspection report 824 Colorado—Production 231	Demurrage, I. C. C. ruling on 714
Carbon diovide Fighting mine fires with . *440	COKE, See also "United States." "Trade."	Department of Mines
Carbon dioxide for mine fires	-Byproduct stocks 80	Clevenberg
—Gear-driven fan	-Crumb. Discussion	Distillation, low temperature. Lamie*171 Distributing, cost, coal 44
Care	-Hungary, imports and exports 904	Distributing, cost, coal
—Assigned27, 115, 152, 189, 605, 642, 679, 713, 754, 941, 973 (e) 91, 271	—Hungary, imports and exports 904 —Low temperature distillation. Lamie. *171 —More or less domestic coke (e) 874	Dividends, railroad coal companies
—Changes in design mine. Gillette &655	- More or less domestic coke (e)	Docks, northwest, freight rates31, 103,
Couples Automotic mine •214 •944	-Production, U. S	Door, emergency
-Door	-Rosedale byproduct ovens. Richardson. *93, *201	
-Number in mines	-Weight cu.ft, sized	Do something, do what? (e) 235 Downthrow or upthrow, which? Discussion. 599
Dump carriage 957	Weight cu.ft. sized	Drainage, mine, tunnel. Discussion 111 Drill, portable electric 908
-Mine, brakes or sprags		Doors, steel explosion
-Retarder, mine		Drilling brass. Radebaugh •669 Drills, churn 593
—Solid end	-Public coal lands leased	Drying from noated coal 277
Cartridge low cost	—Twentymile district	Dump, car carriage
—Mine, brakes or spras 031 —Retarder, mine 976 —Safety block for mine. Brosky *78 —Solid end *238 —Steel, anthracite *591 Cartoon 332 Cartridge, low cost 432 Cartridge, hydraulic 151 Cave, in at Jessup 894	Colo. Fuel & Iron Co	Dust —Coal, discussion Coal Min. Inst 950
Cave-in at Jessup	Combustion, spontaneous	-Coal explosions (e)
Census returns	Commerce Dent of—Intermittency coal	—Ignition at dump
Central Coal & Coke Co., dividend. 974 Central Pa. Coal Producers' Assn. 125 Chain, Two-piece *558 Channel, cost of excavation 64 Check-off, U. S. Coal Comm. 440 Check-off as an issue (e) 163, 199 Check-off, Danger in saya Dr. Eliot. 296	mine operation	-Stone, and safety (e) 818
Channel, cost of excavation	Communist International Moscow 417	-Stone 562 -Transvaal coal 898 -Wetting bug 149 Walls 710, 935
Check-off U. S. Coal Comm	Commutator and core, Building up. 3361 Commutators, Care and repair 106 Commutators, sandpaper for cleaning 402 Commutators, undercutting 288	Dyc. A. V 001
Check-off, Danger in, says Dr. Eliot 296	Commutators, undercutting	Dynamite, proportion nitroglycerine 328
Chester, T	Compensation accident 150	E
Check-off, Danger in, says Dr. Latet. Check-off, union ultimatum 259 Chester, T. Chicago Coal Merchants Assn. 197 Chicago, Wilmington & Franklin Coal Co. Explosion & S24 856	—Insurance, Pa	Earnings, anthracite, classification 49
—Explosion	Vagaries (e)	Earnings (e)
Chutes percentage of pilch for 30%	Competition, The new (e)	504. Correction
Chutes swinging applied to thin seams.	Conductors, maximum current carrying ca-	Earnings, railroads
Gerke *839 Circuit breaker, new oil *213 Circuit Liberties 260	Conductors, maximum current carrying capacity bare copper	
Civil Liberties 260 Claire Furnace Co. 606 Clarksburg Coal Club 161 O47		"Hoisting," "Power," "Locomotive,"
Classification, coal	Congress limiting number mines (e) 579 Connections between meters and trans-	"Lamps." —Alternating vs. direct current595, 615
(inq.)	formers	—Armature burn-outs, Finding cause, 932 —Armature, windings
(inq.) 745 Claude, M. 282 Clemons Coal Co.—Stripping. 282	Consumers price guide	-Block signal for mine track. Rowe *77
Cleveland, Tri-state meeting 961 Clinker trouble, To avoid 16	—Coke manufacture 879	Bonding, importance 966 Bondingvoltage drop *896 Braking, Electric, on mine locomotives. *287
Clemons Coal Co.—Stripping 262 Cleveland Tri-state meeting 961 Clinker trouble To avoid 16 Cloud The real 801 Club City Phila Coaling station 177	Consumption, Coal —Coke manufacture	-Braking, electric as applied to mine loco-
Coaling station	—Railroads30, 252, 370, 557, 893 —Soochan, Russia	—Circuit breaker New oil
Coal Age —Index	Consumption, fuel oil —Public utilities24, 116, 528, 596, 756, 930	-Coils, Testing polarity field
Coal Comm., U. S. —Anthracite operators' statement 26	—Public utilities. 24, 116, 528, 596, 756, 930 —Railroads	Coils, Testing polarity field. 215 Circuits, Resistance of electrical 897 Commutators, Care and repair. 106 Connections between meters and trans-
—Anthracite operators' statement	Contract, Purchase coal 489 Contract, The sacred (e) 127	formers
-Anthracite profits report 747	Convention, Cash value (e) 539 Conveyor. See also "Preparation."	formers
—Brief Utah operators	Belt, for shallow mines. Brosky*917 —Portable belt*360, *436 —Rubber covered belt*380	—Dynamic braking mine locomotive*324 —Electrolysis from current leaks
-Census returns, 1920 824	-Portable belt	-Equipment when electric power fails.
-Civil Liberties report, 407, 417, 447, (e) 426	-Rubber covered belt	Bright •433 —Examination questions 522 —Fuses and fuse block •174
-Cost anthracite to dealers	Coolidge President 414 446 455	-Hoisting, equipment for vertical shaft.
-Coal retailing investigation 26 -Consumers' price guide 26 -Earnings, miners (e) 504 -Engineering and management report 505 -Engineers' valuation report 753 -Ends work Sept. 21 457 -Irregular operation report 451 -Labor turnover, bituminous 601 -Labor report, anthracite 257 260	-Message to Congress 892, 893, Wooton. 892	-Holsting, equipment for vertical shaft. Maxwell
-Engineering and management report 505	Combs, E., trial	—Lightning arresters, Testing, Goodwin. •210
-Ends work Sept. 21	Co-operative Block Coal Co	Low lagging power factor (inq.) 143
-Labor turnover, bituminous 601	Corbin Coal & Coke Co	—Maximum demand (inq.) *144. Discussion
—Legacy (e)	Anthropita to dealers	-Measuring voltage and current*860 -Motors, flashing of haulage355
	—Distributing coal	-Motors, flashing of haulage 355 -Motor generator set, Starting synchronous 932
-Not to tree extra session congress 133 Opposition to report. Wooton 529 Optimistic wage parley 297 -Postpones report. Wooton 31 -Pyramiding by middleman 416 -Purchase coal on contract report 489	Distributing coal 44 Grouting 400 Living anthracite mines 46 Mine supplies Hutchings 952 Production, effect irregular operation 444	nous
—Postpones report. Wooton	Production, effect irregular operation. *444Production, anthracite (e)	—Production by public utilities24, 116, 528, 596, 756, 930 —Protecting transformers and motors from
-Purchase coal on contract report 489 -Report, bituminous wage rates 607 -Report, wholesale and retail trade 639	-Mining 45	-Protecting transformers and motors from
—Report, wholesale and retail trade639 (e) 654	—Returns to Trade Comm. Wooton	single phasing. MacWfiliams
-Report, wholesale and retail trade. 603 -Report, cost production 444 -Report, final 469 -Report, waste in mining 487 -Report, underground management. 691. *733. *773. *811. *845. *957 -Report safety bituminous mining 458	Coupler, Automatic mine car214, 944 Coupling, flexible	Records, keeping electrical. Edwards*586 Relays, auxiliary
-Report, waste in mining 487	Coupling, flexible	—Relay, overload
*733, *773, *811, *845, *957	Credit Pinchot (e)	
Report storage 491 Records transferred 480	Credit Pinchot (e) 385	—Signaling devices. Hay
-Resolution death Pres. Harding 221	Crows Nest Pass Coal Co.—Report39, 125	—Super-power plan. Gealy245
—Strike remedies Labor relations 485 —Supply and stock anthracite 333	Culpable but not criminal (e) 654	worthy
	Cushing, G. (e)	-Welding electric safety
Coal Mining Institute 3 —Program 826 —Meeting *947	Output non monless non machine EAC	Elict, Dr. check-off Elk Horn Coal Corp., report
-Meeting	Output per worker per machine 508 Undercutters and overcutters at Spadra. Ark. 435 Cylinder, Repairing cracked engine. Mac- Williams 782 Czechoslovakia, coal and lignite 330 Strike	Engine cylinder, Repairing cracked. Mac- Williams
Coal. See also "United States," "Trade." 88 —Awards, N. Y. 88 —Gas, new method of making. 141	Cylinder, Repairing cracked engine. Mac- Williams	Engine cylinder, Repairing cracked. Mac- Williams
-Gas, new method of making	Czechoslovakia, coal and lignite 330 —Strike 612	Engineers' Society Western Pa.—Papers.
—Land, Pa. assessment89, 342, 422 —Lands, public	D	Equipment bought without written war-
-Lands, public		Escalators 921
illegal	Dake, W. M. 856 Davis, A. P. 799 (e) 163 Davy lamp 19	Examination Questions and Answers.
	-u., map	Beard

Page	Page	Page
Examinations, Retrograde mining. Thompson	Excess mines (e)	Frog. cast-steel
EXAMINATION QUESTIONS	Excuses not reasons (e) 580	Fuel, motor
-Ala. firebosses-Volume of air passing	EXFLOSION. See also "Dust" "Gases Mine," "Ventilation."	Fulfo pump
—Ala. firebosses—Volume of air passing per minute; mixed lights in gassy mine; shielded safety lamps; safety lamps in gaseous mine; danger signals	-Blackhawk Coal Co	Future for too many mines (e) 910
in gassy mine; why is marsh gas found	—Finding the remedy. Atkins	-
near roof and carbon dioxide near floor?	-Gibson colliery, magazine	O.
—Anthracite foremen, Districts 1-2,—Mix- ture and explosive mixture; Avondale	Glen Rogers 752, 790	Gallup-American Coal Co
disaster; three natural causes govern- ing flow of air in mine; effect regulator		Gardner, E. D. *237, *387, *427
on mine resistance; separate traveling- way; air measurements; quantity of air	—Official responsibility for mine explosions. Discussion 560	Gas, ammonia from coke-oven 281
in circulation; diffusion of gases; strength of props 746. Requirements of law in blasting; thickness of pillars;	Orient No. 1	GASES, MINE
strain on rope; finding depth of shaft; pressure top of dam; reducing accidents. 786	—Reden mines, Poland	Blackdamp become explosive (inq.) 147Exam. questions
-Anthracite foremen, Districts 3-7-Safety	Explosive—Dynamite, constituents 328 Explosives—Fuse don'ts	Ignition gas by sparks (inq.) Luke*711Moving body of gas. Discussion290 Gasolene dipper shovel
lamp, testing for firedamp, require- ments, oils used adjustment mine doors	Explosives, Permissible, Discussion 290 Explosives, sales in U. S76, 322, 501 Exports. See "Trade."	Gasolene production 173
for ventilation, examining mine; dynamite and its constituents 328. Volume	Exports. See "Trade."	Gear drive for mine fan
of air in airway; instructions to pre- vent accidents from blasts; anthracite law requiring foremen to withdraw men under his charge; pillar drawing	P	Gelatt, D. E
men under his charge; pillar drawing	Fan. See also "Ventilation."	Gasolene production 173 Gasolene production 173 Gay Coal & Coke Co., 19 yr record 930 Gear drive for mine fan 15 Gear unit, Helical reduction 142 Gelatt, D. E. 855 Geologic time scale. Ashley 102 Geologic Survey of Prussia 585
in gaseous mine; minimum quantity of air; anthracite law on examination old and new workings	—Gear driven mine	GEOLOGICAL SURVEY, U. S.
-Anthracite foremen, Dists. 8-14—Quantity	-Shaft, Reducing resistance flow air 561 -Speed air through inlet 107	—Cement production23, 106, 322, 450, 642, 961
—Anthracite foremen, Dists. 8-14—Quantity air; permissible explosives; dividing air current; pitch of prop; enlarging shaft; *406. Causes of mine fires and precautions; cubical contents of sinking bucket; first aid; sinking double-	Undershot	-Coal production, world
precautions; cubical contents of sink-	Farmer The	-Consumption coal by public utilities24.
track slope 442	Fatalities —Pa	-Coke production
-Anthracite foremen, Dists, 15 and 16- Mine gases; precautions in blasting	— West Va	-Coke production
when driving two breasts toward each other; place for open light in mine; removing firedamp; safety lamps;	Faulting of inclined seam. Discussion*18.	Geology—Southern W. Va. Clevenberg 14 (e) 2
natural and mechanical ventilation; why is mine ventilation necessary? 823	Federal Bureaus at variance on new mines. 334 Federal Trade Comm.	GERMANY &
-Bituminous, Pa., foremen and firebosses	—Anthracite wholesalers margins report	-Coal and coke delivered to Allies 1922. 302 -Coal reserves
ing accidents; violation mining laws, disobeying instructions; removal of	—Charge midwest retailers unfair methods. 927 —Claire Furnace Co	Coal reserves
dangers building stoppings, writing daily report; precautions in non-	-Compulsory cost returns 828	
gaseous mines; lamps where carbon dioxide is generated 256. Causes	— Injunction suit filing reports	Prices
ing accidents; violation mining laws, disobeying instructions; removal of dangers building stoppings, writing daily report; precautions in nongaseous mines; lamps where carbon dioxide is generated 256. Causes and prevention accidents; drawing room pillars; safeguarding workman in nongaseous mine worked with	—Report anthracite prices . 755, 825, (e) 909 Federated Amer. Eng. Soc. —Amer. Eng. Council	—Ruhr mines, Seizure 302, 463, 648
open lights on discovery of explosive	-Storage committees	—Ruhr strike (e)
gas; causes and prevention of fires in non-gaseous mines; equipment to be	Finton, C. N	Girard royalties (e)
installed with electrically driven	Theoos be examined at working lace Goo	Glen Alden Coal Co., dividend 798
installed with electrically driven pumps; capacity of double-acting	Fireboss should defend safety rights. Luxton 861	Girard royalties (e) 617 Glen Alden Coal Co., dividend 798 Glen Rogers explosion
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Golden C J 115 *294
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton 861 Firedoors in coal mines (e) 617 Fires. See also "Explosions." 966 —Bitner, Carbon dioxide fights, Jones. 3, 132	Goives, to avoid accidents, suitable
pumps: capacity of double-acting pump	Fireboss should defend safety rights Luxton S61	Goives, to avoid accidents, suitable
pumps: capacity of double-acting pump	Fireboss should defend safety rights Luxton 861	Goives, to avoid accidents, suitable
pumps; capacity of double-acting pump	Fireboss should defend safety rights Luxton S61	Goives, to avoid accidents, suitable
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Goives, to avoid accidents, suitable
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Goives, to avoid accidents, suitable
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Goives, to avoid accidents, suitable
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton (a) (b) (c) (c) (c) (d) (d) (d) (e) (d) (e) (e) (e) (e) (e) (e) (e) (e) (e) (e	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton (a) (b) (c) (c) (c) (d) (d) (d) (e) (e) (e) (e) (e) (e) (e) (e) (e) (e	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps; capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up
pumps: capacity of double-acting pump	Fireboss should defend safety rights. Luxton	Going up

Page Page	Page	Lehigh Valley Coal Co. Daving and destrict
Herrin 80, 123, 152, 225, 407, 456, 535, (e) 425 499, 580, 606	Kanawha Coal Operators' Assn	Lehigh Valley Coal Co.—Drying out electric mine locomotive
Hodges, F	Kansas	Leland Coal Co., expands
HOISTING. See also "Haulage," "Power," "Electricity," "Safety," "Rope."	—Co-operative mining 676 —Industrial Court 189, 329, 456 —Machine scale 186, 575	Lick Creek mine unionization 80
n to challow coams	—Machine scale	"Life in a West Va Coal Field"
Converge bolt we soraper 890	—Production	Lightning artificial
	Karapetoff. Prof. V	Lights, open, ignite gas
-Equipment for vertical shaft. Maxwell. *581	cussion	
Reight *433	Kentucky	France
-Exam. questions	-Assessment 575 -Machine mined coal 942	-Pikeview
Record hoists	—Men employed	"I Indochine Minimal!
—Skip at Gallup-American. Cooley*165, *237 —Vertical shaft hoisting, equipment for.	- Production	LifeColli Coal Co —Substation automatic
Maxwell	-Underground loading machines 762 -Unionizing Harlan and Hazard 894	Lineman, hose to protect
008	—Wage cut, southeastern 678	Lineman's rubber gloves
Hoover, H	L	Loaders, Mechanical, Union Pacific Coal Co. 934
	LABOR —Address J. Brydon	Lingering doubt (e) 837 Loaders idle through lack haulage control. 811 Loaders, Mechanical, Union Pacific Coal Co. 934 Loaders, underground 526 Loading boom, flexible 1174 Loading Machine 9733
House Time to clean (e)	—Daily output per employee, Southern Pa. 349 —Days worked anthracite mines 49, 330	Loading machine with caterpillars and
Houses, company owned	—Earnings, anthracite, classification 49	Loading, Urge early coal 967
Housing, Gallup-American Coal Co. Cooley. 427 How different (e)	-Earnings of coal miner. Bezanson *880	640, 850, 916
Hudson Coal Co. —Slope conveyors	—Employee, classes southern Pa	Locomotives —Axle collar
—Slope conveyors	—Insurance, Group. Sparks	-Axle collar
Humidification mine air	production	—Electric braking on mine
220 001	—Miners drawing lots for working places. Discussion	
Hunt. E. E	-Montana mine employees	Southern Pa. 348 Storage battery. Gealy 129 Taken up mountainside. Paul 105
Hydraulic ram (inq.)	—New England, wages and hours	—Thes removed
nydro-naphtualene	—Number employees Lynch mine 542 —Number men, Canadian mines 577	Low temperature carbonization177, 350, 889 Low temperature distillation. Lamie•171
1	—Preference in employment	Lubricator, Safety grease
Ice mine	-Number men, Canadian mines 577Number men, Canadian mines 577Preference in employment 725Report. Coal Comm. 257, 260, 407, 417, 447, 449, (e) 426Soochan collieries, Russia 509	Lubricants for electrical equipment401 555
Ice mine 400 Ignition gas by sparks (inq.) Luke•711 Ilgner-Ward-Leonard system for large hoists. Chadbourne 659	Strike anthracite 371 373 374 415.	Lundale
Illinois	Agreement ratified	M
—Central Control Board	Strike, Czechoslovak	McMenimen, W. L., remarks on labor.
—Production	Strikes, Pa., anthracite, 1918-22 330	Wooton 329 Machine mining (e) 802 Machine shop, Gallup-American 427
—Shipping coal via Big Muddy River 714 —Single policy committee (e) 579	-Strikes, Pa., anthracite, 1918-22. 330 -Strike remedies, Coal Comm. 485 -Strikes. 88, 160, 233, 304, 576, 834, 963 -Turnover, bituminous, Coal Comm. re-	Madeira-Hill Coal Min. Co124, 828,
-Union fights modern machinery 493 Illinois Coal Operators' Assn 528	-Turnover, oltuminous, Coai Comin re- port	Madison Coal Corp.—Safety switch at slope
Illinois Min. Inst.—Meeting 827 Illinois—Wisconsin Retail Coal Merchants	—Wage competition (e) 909 —Wage cut, Ky. 678	mouth
Assn		Maher Collieries Co. Explosion 285. Discussion
Immigration conference	Wages, anthracite	—Explosion 285. Discussion 519 —New issue of bonds 536 Maintenance men, agreement 374
Indiana	chines	Mammoth Coal Co
Freight rates	-Wage increase Welsh miners 158	mines691, *733, *773, *811, *845, *957 Map—Ohio river and coal tributaries 140
-Mines employing fewer than 10 men 934	Laboratory, high voltage testing*211 Ladder, safety*592	maryland bulke
—Prices	La Follette performs without Calder (e) 838 Lake dumpings	Massachusetts —Boycott anthracite (e)
—State first aid meet	Lake Erie, bituminous loadings. 121, 296, 640, 850, 914	—Joint special coal committee 685 —Pure coal law
India, British, coal production	Lake shipments 869	—Pure coal law 24 —Strike precautions 232, 268 —Warriner answers boycott 258
Indo-China, stripping 207 Injunction, Joint Mine case. 334 Inspector, authority mine Discussion. 326	LAMPS, MINERS	Maximum demand indicator
	-Carbide lamp, Peril in use of when test- ing for gas. Luxton	METHODS OF MINING See also "Haul-
Instruction, coal mining	ing for gas. Luxton	age," "Hoisting," "Electricity," "Power," "Timbering," "Pumping."
Insurance, Ground. Sparks	Entry of air to safety lamps. Discussion. 146	-Exchanging four entry for two entry
Insull public-utility interests 568 Insurance, Ground. Sparks 247 Insurance, Group Walsh 665 Insurance on workers, To force employers	Discussion	-Exchanging four entry for two entry system (inq.) Berkovitz
Intl. Mine Rescue Standardization Comm. 180	— Flame safety lamps. Ashworth 636	—Developing two seams on steep pitches.
	—Safety cap lamp. Edison	Discussion
Anthractic rate hearings. 115, 604, 714, 756, 788, 856, 895, (e) 727 —Assigned cars: .27, 115, 152, 189, 457, 605, 642, 679, 713, 941, 973	Lathe Single speed bench	Machine mining in steep pitches (inq.) Strain
605, 642, 679, 713, 941, 973	Law of mixtures applies to volumes 170 Lawmakers await Pinchot conference state executives. Wooton	—Swinging chutes applied to thin seams.
-Demurrage, ruling on 714 -Hillsboro vs. Big Four 189 -Ohio-W. Va. rate case 81	LAW. See also "Compensation."	Gerke
-Uruers suspension certain tariffs 560	-British Columbia, mine inspector 326	—Working two steeply pitching seams. Discussion
-Virginian Ry. decision (e) 1, 801, Rehearing567, 607, 713, 754, 941	—Electric locomotives operated by trolley wire 600	Discussion
Investment engineering (e)	-Equipment bought without written war- ranties	Methods, New, need new public viewpoint
Idwa —Isnition coal dust at dump 209	-Exam. questions	Mexico coal for Canada 161
Production 797 Iron Age 345 Island Creek Coal Co.	-Mass. pure coal	Miami No. 10 team
Dividend	—Safety lamps	Midwest Coal Co., explosion
Report 650 Vertical shaft hoisting Maxwell 581 Italy—Production coal and lignite 330	—Virginia decisions	*203, 204
Production coal and lignite 330	Legislation, analysis of Coal Comm. pro- posals	-Meeting. Davidson
	posals	Miners' Federation Gt Britain 334
Jack, timber	seen as foretaste coal. Wooton 927 Legitt Creek Anthracite Co., car door 872 Lehigh & Wilkes-Barre Coal Co.	Mines closed down
Jackson Walker Coal & Min. Co329, 456, 825	Lehigh & Wilkes-Barre Coal Co. —Dividend	Mines, future for too many (e)
Japan Earthquake (e) 456, 825 Joints, Leaky, in pipe lines (inq.) 441 Jugoslavia, production coal 330 Luctice takes ridgs (e) 272	—Sale coal stock	-Freight rates
Jugoslavia, production coal	— Dividend 124 — Sale coal stock 261, 528 — Strike 160, 536 Lehigh Coal & Navigation Co.—Summit Hill fire 724	—Freight rates

	Page	
Montana —Leasing public coal land	Obituary—Continued	Powdered coal. See "Pulverized."
-Production coal	-Savage M. 344 -Shanklin, N. 726 -Sharpe, T. L. 869 -Smith, J. R. 384 -Spier, L. H. 344 -Steinmetz, Dr. C. P. 675 -Sfeward C. W. 426	Powderly-Coalbrook Safety Institute most
Mount Jessup Coal Co., cave-in. 894 Motor. See "Electricity."	—Sharpe, T. L	Power show
Motor. See "Electricity."	—Spier, L. H	POWER. See also "Boiler," "Electricity."
Moving picture, mine cave-in. Discussion. 110 Morgan, Dr. J. J. 177 Mule collar	-Steinmetz, Dr. C. P 675	-Advantages purchased power. Schaffer. 818 -Alternating vs. direct current 595
Mule collar*662	Mayles D II	-Consumption at Lynch
Mules, southern Pa	- Taylor, B. U. 197 - Taylor, D. 344 - Thedford, T. 799 - Thomas, C. J. 384 - Walker, F. W. 125 - Ward, T. 652 - White, V. 384 - Wilkham, P. W. 688 - Williams, H. G. 466 - Wilson, C. R. 366	-Consumption at Lynch 544 -Demand charge on power bill (inq.) 144
Hunes, Boutstern 1 to	—Thedford, T	
N	Walker, F. W	Bright
N.	—Ward, T 652	plant Means
Names coal mines, queer	-White, V	-Low lagging power factor (ing.) 143
Naphtha, solvent, Franklin plant*309 Natl. Academy Political Science 765, 789	-Williams, H. G	-Modernize mine power house. Butcher
National Mining Co.—Carbon dioxide for		-Navajo plant turns waste piles into
fire in refuse pile 134	Oceanica, production coal	power Cooley
Nationality anthracite mine workers 47 Nationalization coal mines	Oddie to base legislation on Comm. report.	
	Wooton 964	—Southern Pa. field, Ashmead347 —Standardization underground transmis-
NATIONAL COAL ASSN, —Bituminous Operators' Special Comm 603	Official responsibility for mine explosions. Discussion	-Standardization underground transmis-
—Chairmen of committees	O'Gara Coal Co	sion, Lee
—Finance committee 343	Ohio —Contracts awarded institutions 334	
—Foreign trade committee	—Freight rates 81	—Super-power plan. Gealy *245 —Switch, time, on control 932
-Meetings directors and committees 527	-Railroad connections	—Waste in antiquated power plants 765
-Membership committee	Oil burning plants, Minneapolis 38	Praetical moves (e) 307
—Publicity committee	Oil. creosote	PREPARATION
Railroad relations committee	Oil, light, Franklin plant	Drying froth-floated coal Tupholme 277
Natl. Industrial Conference Board260,	Oil, lubricating 173 Oil vs. anthracite (e) 837	-Picking tables, rubber covered belt con-
Natl. Retail Coal Merchants Assn. 856, (e) 236	Oil vs. coal. Wood 935	veyors
-Advisory committee	Oklahoma—Coal production	Screen, shakes and vibrates
-Convention	Optimist, perennial (e)	day plants
		day plants •213 —Screening, dual •237 —Washer removes refuse in coal as it
Astronal Safety Council	P	travels. Kersten847
—Papers		Presidential year (e)
Nebraska governor buys coal at mine 536	Panama Canal shipments	President, Death of the (e) 199 President on coal (e) 773
	Panhandle Min. Inst. West Va 861	President on coal (e)
Netherlands, production coal and lignite 330	Panorama: small corner of (e) 838	PRICES
New England Coal Dealers' Assn	Parker, E. W	—Domestic
New Field By-Product Coal Co.—Removal	Pascoe, S	—Indiana 762
worn locomotive tires	Patents90, 126, 198, 234, 270, 502, 538, 616, 652, 726, 905, 973	Maine
New York price inquiry527, 566, 607, 641, 797, 835	Pay, More, less coal (e) 539	-rian rejected to curb hard coal 827
New York State Coal Merchants Assn.	Peat investigation 424	—Report Federal Trade Comm
—Addresses 446	Pennsylvania —Coal for public institutions 423	Toledo, Ohio 576 Prize best battery locomotive 739
Program	—Assessments, coal land89, 342, 422, 614, 650, 717, 871, 906, 943	Prize best battery locomotive 739
Wooton 605	614, 650, 717, 871, 906, 943 —Compensation bureau, Dist. 1 686	PRODUCTION. Coal if not otherwise
North Dakota —Elevating graders at strip pit*738	—Compensation insurance 961	specified.
-Freight rates on lignite	—Depth southern field. Ashmead*347 —Fatalities	-Alabama
Northeast Kentucky Coal Assn. 905 Northern West Va. Coal Operators' Assn. 905	-Giant Power Board 568	—Africa
Northern West Va. Coal Operators' Assn.	— Giant Power Board 568 — Geologic time scale, Ashley 102 — Men employed, days worked 49, 330	-Asia
Northwest Dock Operators' Assn31	-Men employed, days worked49, 330 -Mine-cave bills160	—Australia
Number anthracite mine workers 45	—Production	—Belgium 330
	-Reports mine inspectors	—Bituminous coal producers classified 885 —British India
0	-Reserves Somerset county 763	Bulgaria
OBITUARY	—Somerset county strike settled. 304 —Tax, treasurers' report	-Canada89, 125, 161, 197, 330, 343, 384, 424, 537, 577, 615, 725, 764,
	Tax, treasurers report	799, 836, 871, 907
	-Tax anthracite	100, 000, 011, 001
—Ball, E	—Tax anthracite	—Cement23, 106, 322, 450, 642, 961
—Ball, E	— Tax anthracite 400 576 — Thick Freeport seam 739 — Trees planted 724 — Valuation coal land, Scranton 798	—Cement23, 106, 322, 450, 642, 961
—Ball, E. 726 —Beury, C. C. 233 —Brady, J. 688 —Bresnan, J. R. 197	— Tax anthracite 40, 57 — Thick Freeport seam 739 — Trees planted 724 — Valuation coal land, Scranton 798 Penn. Coal & Coke Co., earnings 686	— Cement .23, 106, 322, 450, 642, 961 — Chile .330 — Coke .677, 879 — Colorado .88, 231, 464
—Ball, E. 726 —Beury, C. C. 233 —Brady, J. 688 —Bresnan, J. R. 197 —Browning, M. S. 89 —Burgis, J. 244	- Tax anthracite	— Cement 23, 106, 322, 450, 642, 961 — Chile 330 — Coke 677, 879 — Colorado 88, 231, 464 — Costs Anthracite (e) 368
Ball. E. 726 -Beury, C. 233 -Brady, J. 688 -Bresnan, J. R. 197 -Browning, M. S. 89 -Burns, J. 344 -Bussey, C. C. 4 384	- Tax anthracite 480, 570 - Thick Freeport seam 739 - Trees planted 724 - Valuation coal land, Scranton 798 Penn. Coal & Coke Co., earnings 686 Penn. Coal Co. 686 - Officials inspect No. 14 colliery 816 - Strike 715	— Cement 23, 106, 322, 450, 642, 961 — Chile 330 — Coke 677, 879 — Colorado 88, 231, 464 — Costs Anthracite (e) 368
Ball. E. 7226 -Beury, C. 233 -Brady, J. 688 -Bresnan, J. R. 197 -Browning, M. S. 89 -Burns, J. 344 -Bussey, C. C. 4 384 -Caldwell, J. L. 688 -Caldwell, J. L. 688	- Tax anthracite 480, 570 - Thick Freeport seam 739 - Trees planted 724 - Valuation coal land, Scranton 798 Penn. Coal & Coke Co., earnings 686 Penn. Coal Co. 686 - Officials inspect No. 14 colliery 816 - Strike 715 Penn. Coal Producers Assn. 616 Penn. State Colleges—Coal mining classes 246	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648
Ball. E. 726 -Beury, C. C. 233 -Brady, J. 688 -Bresnan, J. R. 197 -Browning, M. S. 89 -Burns, J. 344 -Bussey, C. C. 4 384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688	- Tax anthracite	-Cement. 23, 106, 322, 450, 642, 961. -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite. 330
Ball. E. 7226 -Beury, C. C. 233 -Brady, J. 688 -Bresnan, J. R. 197 -Browning, M. S. 89 -Burns, J. 344 -Bussey, C. 4384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616	- Tax anthracite	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball, E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Buris, J. 344 Bussey, C. C. 384 -Caldwell, J. L. 688 -Cannon, C. S. 270 Clark, J. A. 688 -Conkle, W. H. 616 -Comell, W. L. 894 -Cropsey, F. J. 161	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Buris, J. 344 Bussey, C. C. 384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616 -Connell, W. L. 894 -Cropsey, F. J. 161 -Cunningham, T. 616 -Cunningham, T. 616	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
-Ball E	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball. E. 726 -Beury. C. C. 233 -Brady. J. 688 -Bresnan, J. R. 197 -Browning. M. S. 89 -Buris. J. 344 -Caldwell. J. L. 688 -Cannon. C. S. 270 -Clark. J. A. 688 -Conkle. W. H. 616 -Connell. W. L. 894 -Cropsey. F. 161 -Cunningham. T. 616 -Dana. E. J. 384 -Davidson. B. C. 578 -Dubois. P. L. 468	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball. E. 726 Beury. C. C. 233 Brady. J. 688 Bresnan, J. R. 197 Browning. M. S. 89 Burns. J. 344 Bussey. C. C. 4384 -Caldwell. J. L. 688 -Cannon. C. S. 270 -Clark. J. A. 688 -Concell. W. H. 616 -Connell. W. L. 8894 -Cropsey. F. 161 -Cunningham. T. 6616 -Dana. E. J. 384 -Davidson. B. C. 578 -Dubois. P. L. 466 -Farr. B. F. 973 -Ferguson, A. A. 973	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 4384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616 -Connell, W. L. 894 -Cropsey, F. J. 161 -Cunningham, T. 616 -Dana, E. J. 384 -Davidson, B. 578 -Dubois, P. L. 466 -Farr, B. F. 973 -Ferguson, A. A. 9973 -Fitzer, J. R. 726	Thick Freeport seam	-Cement. 23, 106, 322, 450, 642, 961 -Chile 330 -Coke 677, 879 -Colorado 88, 231, 464 -Costs, Anthracite (e) 308 -Czechoslovakia, coal and lignite. 330 -Electricity by public utilities 116 -France 67, 122, 302, 381, 498, 612, 648 -Gasolene 173 -Germany, coal and lignite 330 -Greece 330
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616 -Connell, W. L. 9894 -Cropsey, F. J. 161 -Cunningham, T. 616 -Cunningham, T. 616 -Dana, E. J. 384 -Davidson, B. C. 578 -Dubois, P. L. 466 -Farr, B. F. 973 -Fitzer, J. R. 726 -Fitzsimmons, T. 344 -Fleming, A. B. 652	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 — France 67 122 302 381 498 612 648 — Gasolene 173 330 — 648 <t< td=""></t<>
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 4384 Caldwell, J. L. 688 Cannon, C. S. 270 Clark, J. A. 688 -Conkle, W. H. 616 Connell, W. L. 894 -Cropsey, F. 1616 -Cunningham, T. 6616 -Dana, E. J. 384 -Davidson, B. C. 578 -Dubois, P. L. 466 Farr, B. F. 973 -Ferguson, A. A. 973 -Fitzer, J. R. 726 -Fitzsimmons, T. 344 -Fitzsimmons, T. 3652 -Fitzsimmons, T. 3652 -Fitel, T. H. 538	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs, Anthracite (e) 308 308 — Czechoslovakia, coal and lignite 310 — Electricity by public utilities 116 — France 67 122 302 381 498 612 648 — Gasolene 178 478
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Buris, J. 344 Bussey, C. C. 4 384 -Caldwell, J. L. 688 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616 -Connell, W. L. 894 -Cropsey, F. J. 161 -Cunningham, T. 616 -Dana, E. J. 384 -Davidson, B. C. 578 -Dubois, P. L. 466 -Farr, B. F. 973 -Fitzer, J. R. 726 -Fitzer, A. B. 652 -Friel, T. H. 538 -Gilman, R. E. 973 -Gilman, R. E. 973	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs, Anthracite (e) 308 308 — Czechosłovakia, coal and lignite 310 — Electricity by public utilities 116 — France 67 122 302 381 498 612 648 — Gasolene 330 - 64 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 330 - 67 - 67 - 67 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 330 - 94 - 94 - 330
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 4 384 -Caldwell, J. L. 688 -Cannon, C. S. 270 -Clark, J. A. 688 -Conkle, W. H. 616 -Connell, W. L. 894 -Cropsey, F. 161 -Dana, E. J. 384 -Davidson, B. C. 578 -Dubois, P. L. 466 -Farr, B. 726 -Fitzer, J. R. 726 -Fitzer,	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 France 67 122 302 381 498 612 648 649 833 641 649 833 641 640 640 640
Ball. E. 726 Beury. C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 4384 —Caldwell, J. L. 688 —Cannon, C. S. 270 —Clark, J. A. 688 —Conkle, W. H. 616 —Connell, W. L. 9894 —Cropsey, F. 161 —Cunningham, T. 6616 —Dana, E. J. 384 —Davidson, B. C. 578 —Dubois, P. L. 466 —Farr, B. F. 973 —Fitzer, J. R. 726 —Fitzer, J.	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs, Anthracite (e) 308 308 — Czechoslovakia, coal and lignite 330 — Electricity by public utilities 116 — France 67 122 302 381 498 612 648 — Gasolene 173 — Germany, coal and lignite 330 — 330 — Greece 330 — 330 — Greece 330 — 94 — 98 33 — 101 — 101 — 101 — 101 — 102
Ball. E. 726 Beury, C. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 384 —Caldwell, J. L. 688 —Cannon, C. S. 270 —Clark, J. A. 688 —Conkle, W. H. 616 —Connell, W. L. 8894 —Cropsey, F. 161 —Cunningham, T. 6616 —Dana, E. J. 384 —Davidson, B. C. 578 —Dubois, P. L. 466 —Farr, B. F. 973 —Fitzer, J. R. 726 —Fitzer, J.	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Costs, Anthracite (e) 308 231 468 — Czechosłovakia 301 and lignite 330 — Electricity by public utilities 116 France 67 122 302 381 498 612 648 — Gasolene 130 48 612 648 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648
Ball. E. 726 Beury C C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 384 Caldwell, J. L. 688 Cannon, C. S. 270 Clark, J. A. 688 Conkle, W. H. 616 Connell, W. L. 894 Connell, W. L. 894 Connell, W. L. 9894 Con	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Coste, Anthracite (e) 308 231 468 — Czechosłovakia, coal and lignite 330 310 488 116 478 488 612 648 488 612 648 488 612 648 488 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 648 648 648 648 648 648 648 648 648 648 648 648 641 648 649 833 648 641 641 648 641 641 641 641 641 641 641 641 641 641
Ball. E. 726 Beury. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey. C. C. 384 Caldwell, J. L. 688 Cannon, C. S. 270 Clark, J. A. 688 Connell, W. L. 688 Connell, W. C. 688	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Coste, Anthracite (e) 308 231 468 — Czechosłovakia, coal and lignite 330 310 488 116 478 488 612 648 488 612 648 488 612 648 488 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 648 648 648 648 648 648 648 648 648 648 648 648 641 648 649 833 648 641 641 648 641 641 641 641 641 641 641 641 641 641
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Coste, Anthracite (e) 308 231 468 — Czechosłovakia, coal and lignite 330 310 488 116 478 488 612 648 488 612 648 488 612 648 488 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 648 648 648 648 648 648 648 648 648 648 648 648 641 648 649 833 648 641 641 648 641 641 641 641 641 641 641 641 641 641
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 330 — Coke 677 879 — Colorado 88 231 464 — Coste, Anthracite (e) 308 231 468 — Czechosłovakia, coal and lignite 330 310 488 116 478 488 612 648 488 612 648 488 612 648 488 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 612 648 648 648 648 648 648 648 648 648 648 648 648 648 648 641 648 649 833 648 641 641 648 641 641 641 641 641 641 641 641 641 641
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	Cement
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 France .67 122 302 381 498 612 648 — Gasolene
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 France .67 122 302 381 498 612 648 — Gasolene
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 France .67 122 302 381 498 612 648 — Gasolene
- Davius P. L. 4466 - Farr. B. F. 973 - Ferguson, A. A. 973 - Fitzer, J. R. 726 - Hall, L. M. 973 - Hall, L. M. 973 - Hirsch, G. 161 - Hobart, B. 762 - Hood, K. 7578 - Humphries, R. J. 764 - Leventry, W. 197 - McChesnev F. E. 538 - McCook, W. F. 306 - McGowan J. H. 306	Thick Freeport seam	— Cement 23 106 322 450 642 961 — Chile 677 879 — Colorado 88 231 464 — Costs Anthracite (e) 308 — Czechoslovakia coal and lignite 330 — Electricity by public utilities 116 France 67 122 302 381 498 612 648 — Gasolene 17 — Germany coal and lignite 330 964 48 330 Greece 330 930 330 904 48 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 904 330 330 424 430 330 430 430 430
Ball. E. 726 Beury. C. 233 Brady, J. 688 Bresnan, J. R. 197 Browning, M. S. 89 Burns, J. 344 Bussey, C. C. 384 —Caldwell, J. L. 688 —Cannon, C. S. 2270 —Clark, J. A. 688 —Conkle, W. H. 616 —Connell, W. L. 161 —Connigham, T. 616 —Connell, W. L. 484 —Capavidson, B. C. 578 —Dubois, P. L. 466 —Farr. B. F. 973 —Ferguson, A. A. 973 —Fitzer, J. R. 726 —Fitzsimmons, T. 344 —Fitzer, J. R. 726 —Fitzsimmons, T. 365 —Fitzsimmons, T. 365 —Hall, L. M. 197 —Hall, L. M. 197 —Haltings, H. S. 973 —Humphries, R. J. 764 —Hobart, B. 652 —Hood, K. 973 —MecChesnev, F. 366 —McGowan, J. H. 306 —McChesnev, F. 306 —	Thick Freeport seam	Cement

Page	Page	Page
Prospecting coal, permits, U. S. 67 Pryde, G. 80 Psychology for coal merchant (e) 200 Public, inarticulate (e) 773 935	Roof, Supporting, over roadway. Discussion	Small but irritating (e) 345 Smith, Gov. begins coal inquiry 527 Smith, G. O. 294, 480, 787 Smokeless Coal Operators' Assn. of West 652, 726, 927, 929
Public's mind, Preparing (e) 235 Pulverized coal, determination fineness 661 Pulverized coal size of 14 Pulverized fuel for boilers 315 Pulverized coal as fuel 658	Rope, hoisting	Small but irritating (e) 345 Smith, Gov. begins coal inquiry 527 Smith, G. O. 294, 480, 787 Smokeless Coal Operators' Assn. of West Va. 652, 726, 927, 929 Socket couples broken rope *360 Solder pot, electric 628 Soochan, Coal of, Tolmachoff *509 Southwestern Interstate Coal Operators' Assn. 464, 607
PUMPS AND PUMPING Automatically controlled pumps. Gealy.*39:2 Ball-bearing pump, self priming*174	Royal Fuel Co.—Two Ians ventulate sepa- rate areas 842 Royalties, Why not fix Girard (e) 617 Rubber gloves, linemen's 592 Rumania, production coal 330	Spadra, Ark., coal cutters
dirt solids 976 —Centrifugal pump motor 897	RUSSIA	—Production 330 —Shipments 940 Splice, Eliminating 369 Springfield to St. Joseph rate cut 678 Sprinkling tanks, electric 899
- Centrifugal Single-stage double-suction. * 305 - Centrifugal vs. reciprocating * 985 - Column line breaks prevented * 437 - Exam, questions * 112, 292 - Gathering pumps * 658, * 740 - Hydraulic ram (inq.) * 673 - Shaft water * 399 - Siphons, limitations, (inq.) * 521 - Vacuum pump, small * 872 - Punishment—not dissolution (e) * 345	—Coal reserves 17 —Government operation (e) 874 —Production, coal 330, 857 —Soochan coal, Tolmachoff *509 Ryan, J. T. *948	Spuds (e) 653 Squeeze can be helpful (e) 617 Stacked deck (e) 765 Standardization (e) 539 Standardization underground transmission.
Siphons, limitations, (inq.) 521	St. Louis Coal Co	Lee 923 Standardized coal screen *213 Standardized track gages 594 Stark, P 527 Statistics Business (e) 945
9	-Block for mine cars. Brosky *78	Statistics, Dominion Bureau
Quid pro quo (e)	-Dust, stone, (e)	Steinmetz, Dr. C. P., obituary
R Radium mine, flooding892, 942	Discussion 217	Stokers, Navajo No. 5 mine
Rail bonding	-Hose to protect lineman	Stoppings, concrete 955 Stoppings, projected concrete for Brosky 955 Stoppings, material for airtight or fireproof, 562
—Baltimore & Ohio	— Law, Obeying spirit. Discussion	Storage, coal discussed by A.S.M.E 894 Storage. Tryon and McKenney *924 Storage bituminous and anthracite *79.
Control outs transportation to Torsey City 650	Posters on mine cars	Storage, Coal Comm. report
- Chesapeake & Ohio 124, 126, 162, 305, 423, 538, 724, 836, 905 - Chicago, Milwaukee & St. Paul 929 - Chicago, Rock Island & Pacific 38 - Consumption coal and fuel oil 30, 252, 803	Stunts help miners protect themselves. •911 Suitable gloves, caps and shoes to avoid accident	Strikes pay, Do (e) 653 Stripping, See also "Methods of Mining." 207 Strippings, Indo-China 282 Stripping, Kansas 282 Stripping, lignite No, Dak. 6738
—Decision litigation spur track	-Track device. Brosky	
	-Welding and cutting, electric	Substations at mines, automatic. Borland. *71 Substitutes for unions (e)
Freight carried, U. S	Sault Ste. Marie, coal traffic	Substitutes (e) 346 Sump clean of coal Bowker 353 Summit Hill mine fire 536 Supplies, buying and care of mine Hutch
—Locomotives, new and repaired306, 384, 424, 502, 578, 652, 688, 726, 836—Louisville & Nashville341, 466, 576,	School, Natl., Commercial and Trade Executives 200 Screen, See also "Preparation." Screen, Cottrell, wet and dry 944	ings 952 Supplies, Keep eagle eye on mine (e) 946 Supplies, mine. Discussion 363 363 363
New Mexico R.R	Screen for wet and dry fines	Sweden, production coal 330 Switch, Automatic track • 780 Switch, Safety, at slope mouth • 284 Switch Safety, at slope mouth • 284
—Pennsylvania	Screening, dual, arrangement 237 Screenings, pumping 802 Screenings, weight and per cent (ing.). 599	Switches, electric, located by white markers. 438 Switzerland, production coal
Planning a nation's transportation (e). 128 Railroads deliver (e)	Screws from burning, preventing attachment	Taft, L
—Segregation of railroads and coal lands. 26 —Shipments121, 123, 162, 304, 305,	Selling Ford coal (e)	Taking up coal in serious way (e) 689 Tape, adhesive strength 931 Tar from 50 million tons of coal 173
—Stored coal	substitute 694 Separator, spiral, Pardee 316 Shafts	Tar separator *312 Tax Assn. Natl. 423 Tax, coal, Kentucky 38, 88 Tax, coal sales West Va. 537 Tax, land, anthracite 89, 342, 422, 614, 650, 717
Rails extension and removal Downing \$808	-Depth, finding 786 -Design and sinking Johnson 397 -Designed to make bunton replacements easy 967	650, 717 Tax, Pa. anthracite
Raleigh Wyoming Coal Co., explosion. 752, 790 Ram, hydraulic (inq.) 673 Rate sheets must be submitted 55 Reading segregation 24, 124, 650, 756, 795, 835, 907	-Enlarging	Tennessee Freight rates
Records mechanical and electrical coun-	well	Texas—Contracts, state
Red Ash Coal Co.—Fire *133	-Upraise. Powell	Thacker-Pocahontas Coal Co. 651 Third line of defense (e) 307 Thompson, S. E. (e) 838 Tidewater Coal Exchange 762
Reel, spring, for cable 592 Refinery, Franklin, Richardson *309 Refinery, Rosedale, Richardson *201 Reforesting coal areas 89	Shafting, Flexible drive	Ties, steel mine track (inq.) Walker 405. Discussion
Reforesting coal areas 89 Regulation of the consumer (e) 654 Relativity (e) 127 Relay, universal thermal 17 Relays auxiliary 740 Report, anthracite, Coal Comm. 43, 116, 117, 151 (e) 41 42 127 Press com-	York	—Conserving timber 862 —Creosoting 698, Clark *357 —Crossbars on eyebeam stringers *363
ments com	Shipments, Panama Canal	- Methods will save lives, coal and lumber. Gray
ments	Shoes, steel brake 879 Shoes to avoid accidents, suitable 862 Shop, repair, Gallup-American, Cooley 427 Shovel, compressed air 591	— Methods will save lives, coal and lumber.
Rescue meets. See 'First Aid.' Rescue, mine, apparatus. 180 Rescue, mine, apparatus. 180	Shovel, gasoline dipper 436 Shovels, steam, upkeep costs 249 Shovels, Traction wheel mounting for rail- road steam 4170	—Withdrawing mine timber (inq.) *20. Discussion
Rescue stations, foreign	road steam	Tires, steel 620 Toluol. Franklin plant 309 Tonnage underlying coal tract (inq.) 183
Rescue stations, foreign 947, 951 Rescuer self 590 Research, mining U. S. and Gt. Britain 687 Reserves, anthracite 753 Reserves, coal. world 17 Retailers assail Pinchot settlement 456 Restort revolving horizontal 777	Signaling bells *518 Signaling devices, Electric, Hay *953 Silzer, Gov	Toluol, Franklin plant 309 Toluol, Franklin plant 183 Torch, The miner's 889 Towboat C. F. Richardson 1139 Towers, coal, with wooden rollers 633 Town, Where to build mining, Downing 633
Retort, revolving horizontal 7777 Revenue, Govt., mineral leases 197 Rheolaweur 847 Rhodes Fuel Corp. 193 Rio de Janiero, imports 940	Silzer and Ritchie repudiate Pinchot plan 9739 Siphonic pumping (e) 838 Siphon, passing of (e) 766 Siphons, limitations *521. Correction 744 Signor the office of the plan 1878	Track, battery
River coal loading and unloading \$137	Slant road grade (ing.)	Tracks—Extension and removal of rails. Downing
Roed in mine, slant (inq.)	Slate Lynch mine	Town. Where to build mining. Downing. *63 Track. battery .591 Track shifter .249 Tracks—Cast-steel frog .17 Tracks—Extension and removal of rails. Downing .898 Tracks. mine. (e) 346. Martin .351 Traction wheel mounting .316 Traders' Coal Co.—Storage battery charging station .129 Trade Association Activities .126
*253, 254	Slushing, Double drum hoist for908	Trade Association Activities†186

TRADE	United Mine Workers—Continued	Washington
-Exports, Canada28, 89, 384, 577	-Pottsville town locals abolished 798	-Coal publicity campaign 724
Exports, France67, 230, 266, 381, 664, 868	—Tri-district convention 29 —Illtimatum check-off 259	-District 10, peace in
Powerts Commons	—Ultimatum, check-off	-Freight rates
- Exports, Nova Scotia - 27	*547, *553, *875, *917	—Number mine employees
-Exports, United Kingdom. 36, 122, 463, 796	UNITED STATES. See also "Bureau of	Waste, disposal 364 Waste in antiquated power plants (e) 765
-Exports, U. S 36, 158, 194, 340, 463,	Mines " and "Geological Survey "	Waste in antiquated power plants (e) 765
districts	—Budget, annual	Waste in mining 487 Water supply for boilers Navajo mine. 390 Water underground reservoir
-Freight rates hearing at Denver 456	-Explosives, sales of	Water, underground reservoir
-Freight rates anthracite, investigation by I.C.C	-Exports36, 158, 194, 340, 463, 534,	Water, Weight and expansion (inq.) 822
I.C.C115, 604, 714, 756, 788, 850	36. 194 421 612 684	Weightometer, public
162. 225. 384. 424. 466. 538. 578.	-Fatalities22, 222, 370, 565, 752, 858	Welding and brazing. Radebaugh
616, 679, 688, 714, 726, 762, 764,	—Gasoline, production	Weightometer 388 Welding and brazing Badebaugh 988 Welding and cutting Safety in electric. 15 Welding and cutting Safety in gas. 105, 216 Welding and cutting Safety in gas. 105, 216
800, 836, 868, 905, 962	Imports, coal and coke36, 194, 574,	Welding and cutting, Safety in gas 105, 216
—Hungary exports and imports 904 —Imports, Canada	—Mining machines in use	Wedding, oxyacetylene 627 Welding, oxyacetylene, repairs pipe. *741 Welzmiller, Mrs. L. R. 689 Wentz acquires New River Coll. 222 Western Canada Coal Operators Assn. 537 Western Coal Min. Co. vs. Mackie Fuel Co. 575
-Imports, Canada 25, 65, 157, 270, 364, 577	-Production, coal and lignite330, 676	Welzmiller, Mrs. L. R. 689
498, 664, 868	-Prospecting permits, coal 67	Wentz acquires New River Coll
—Imports. Germany	-Public coal lands 136	Western Canada Coal Operators Assn 537
-Imports, Rio de Janeiro 940	—Railroads	western Coal Min. Co. vs. Mackie Fuel
—Imports, U. S. coal and coke36, 194, 574, 684, 868	Utan	Co. 575 West Jellico Coal Co. 383 West Kentucky Coal Bureau 502 West Kentucky Coal Co.—River transport-
Traffic news 40, 90, 126, 162, 182, 234, 306, 344, 384, 424, 466, 502, 538, 578, 616, 652, 688, 726, 764, 800, 836 Transformer. See "Electricity." 596 Transmission efficiency 596	—Brief to Coal Comm	West Kentucky Coal Bureau 502
306, 344, 384, 424, 466, 502, 538,	—Denver & Rio Grande Ry. improvements. 269	West Kentucky Coal Co.—River transport-
578, 616, 652, 688, 726, 764, 800, 836	—Lease, coal lands	ing coal
Transformer See "Electricity."	V	West Virginia
Transmission efficiency 596		
Transportation	Valley Camp Coal Co.—Slope conveyor Kin-	-Available coal area 975 -Condemn efforts to unionize 295
-Aerial tramway. Trabel & Richards*175	loch mine	-Fatalities
—Onio River coal traine, williams137		—Fatalities 871 —Gas. natural, decision 943 —Keeney proposes unionizing 324 —Logan trial 189, 342, 384, 799, 835, 943 —Production 342, 384, 799, 835, 943
—Safety in underground 631	Value Pa, anthracite, 1922 81	-Logan trial189, 342, 384, 799, 835, 943
Transportation	valve, globe	Froduction, coal and coke
Transvaal, Fighting coal dust*898	Vancouver coal nearly exhausted, Mason. *777 Venezuela, production coal	—Sales tax on coal
Treadway, Rep., repeal anthracite tax 854 Tri-district convention	venezueia, production coai	West Va Coal Min Inst
Tri-state meeting. Cleveland 961	**********	—Meeting. Brosky
Tri-state meeting, Cleveland 961 Trolley wheels, Maintaining. Emerson. 860 Trolley wheels, Renewing and lubricating. Grimes 361	VENTILATION. See also "Gases, Mine."	-Papers*3, *63, *132, *171, *917
Trolley wheels, Renewing and lubricating.	-Airways in mines, Multiplying. Discus-	West VaKy. Mine, Mech. & Elec. Engrs.
Trolley wheel, sparking. Parker	sion	-Association made national (e) 579
Tropic Mining Co	-Bituminous mine law. (Pa.) Discussion. 290	Meeting
Truck, Atlas carryali	-Compressed air, ventilating by 598	—Program 528
Tunnel, Longest mine-drainage. Discussion. 111	—During development of mine 325	Program 528 West Va. School of Mines 505, 506 Westmoreland Coal Co., dividend 974 What do miners earn (e) 504. Correction, 715 What will it carry
U	-Equipment when electric power fails.	What do miners earn (e) 504. Correction, 715
•	Bright	What will it cost; what will it earn?
Union Pacific Coal Co., improvements 934	366, 406, 562, 712, 746, 823, 846	What will it cost; what will it earn? Means 918 Meeling Steel Corp., explosion 618 Wheeling Steel Corp., explosion 618 Wheel mounting, Traction 316 White, C. P. 82 White Oak Coal Co 97 White Oak Coal Co 97 Who will read them (e) 69 Winding Gulf Operators Assn 945 Window glass case 975 (e) 83 Winter, Perilous (e) 42 Wolf-Summit mine, gunite stopping 955 Woodward Iron Co, wage adjustment 613
UNITED KINGDOM	-Exhaust vs. blowing slope mine (inq.) 305	Wheeling Steel Corp., explosion
	Fan drive and horsepower on air 859	Whitaker, Prof. J. W
—British coal industry. Wooton 732, 779, 815, 844, 888, 922, 959	Reducing resistance to now of air in tan	White, C. P 828
Cool macanica	shaft. (ing.) *561. Discussion*821	White Oak Coal Co
-Coat reserves 17. -Dust, handling 862 -Exhibition, British Empire 212 -Exports 36, 122, 463, 796 -Flotation, Powell Duffryn mines 277 -Mortality in relation to output 916 British bot back the relation 1799	-Resistance due to bends in airways (inq.)	Who will read them (a)
Exports 36 122 463 796	Holman	Winding Gulf Operators Assn 943
-Flotation, Powell Duffryn mines 277	-Speed of air through inlet of fan. Robin-	Window glass case
-Mortality in relation to output 916	son	Winter, Perilous (e)
	-Two fans at Royal mine. Tescher*842	Women's Activities Assn —W Va exhibit 384
Production, coal 330 Profit sharing at mines 818	Vermilion Co	Woodward Iron Co., wage adjustment 613
-Redding mine, flooding 642	Virginian Ry162, 198, 265, 567, 607,	Wooton, P 236
Redding mine, flooding	713, 754, 941 (e) 1, 801	Woodward Iron Co., wage adjustment. 613 Wooton, P. 236 Wyoming—Public coal land leases 233 Wyoming Anthracite Co. 136
-Stark, P., oldest miner 527	· w	wyoming Anthracite Co
—Tariff, coal trimming 565 —20-ton cars Gt. Western Ry 698 —Wage increase Welsh miners 158		_
-Wage increase Welsh miners 158	Wabash River, concessions for coal under. 613	x
United Mine Workers	Wadleigh, F. R333, 458, 493, 567,	Vuloi Franklin plant
—Allege Communist move control unions 417, 566	Wagner See "Tabor"	Xylol. Franklin plant*308
—Brennan withdraws	Wabash River, concessions for coal under. 613 Walleigh, F. R333, 458, 493, 567, 568, 569, 606, 607, 715 Wages, See "Labor." Walsh, J. J	Y
—Combats co-operative mining 676	Warriner, S. D	
—Contribution Japanese relief fund 465		Yard, Govt. fuel
Executive board meeting 826	Kersten *847 Washery water improves farm land 806	Years life coal in ground
-Herrin mine	Washhouse. See "Bathhouse."	Youghiogheny & Ohio Coal Co.—Emergency power supply433
- Lavot saving machinery opposition 000		

AUTHORS' INDEX

Page	Page	Page
LLAN, W. Retimbering old slope 110	GEALY, E. J. Electric braking mine	PARFITT, I. C. Abnormal roof conditions
shley, G. H. Geologic time scale 102 shmead, D. C. Southern Pa. anthracite. 347 shworth, J. Marsaut type safety lamp. 636	——Storage battery locomotives*129 ——Position coal super-power plan*245	Parker, F. Severe sparking trolley wheel. *707
shworth, J. Marsaut type safety lamp. 636	Position coal super-power plan	Paul. J. W. Davy safety lamp
Flame safety lamps	Gerke, A. Swinging chutes within seams. 839 German, W. J. Clean out slack in under-	Pickett, R. J. Retimbering old slope 110
seam	German, W. J. Clean out slack in under-	Powell, J. W. Working double seam coal. 68 ——Lightening labor upraising shaft*136
Finding the remedy 672 Working three contiguous seams 744	Gillette, G. M. Changes in design mine	— Working two steeply pitching seams. •145 — Well-placed shots in upraise •358
	Goodwin, V. E. Testing lightning arresters. *210	——Steel track ties 871
AIN, H. F. Rescue work at Hunt mine		—Blasting out timbers 784 —Mining seam pitching coal 863 Price M. M. Steam boiler practice, Advance in •767
fire	Timbering methods	Price, M. M. Steam boiler practice,
Answers 432 eda. P. W. Steel track ties 671 eddow, M. S. Suspending feeder cables	wheels	
eddow, M. S. Suspending feeder cables 965		RADEBAUGH, G. Welding and brazing *99
eritry	Hamilton, R. Fighting mine fires with carbon dioxide	— Drilling brass
	Hammond. H. Fire protection, breaker•729 Hay. T. R. Electric signaling devices 953 Herbert, C. A. Inflammation coal and dust	Reed. J. W Changes in design mine cars. *655
ezanson, A. What the coal miner earns*880 dair, J. H. Motor size on mine locomo-	Herbert, C. A. Inflammation coal and dust	Richards, W. C. Aerial tramway
tives 438	at dump	coke ovens
ock, H. Faulting of inclined seam 18 torland, J. E. Automatic substations at	Holman, G. Resistance due to bends in	
owker, G. Keeping shaft sump clean•353	airways	Riley, J. Moving body of gas dangerous. 290
Supporting roof over roadway 303	locomotives287	Robinson, J. R. Speed of air through inlet of fan 107
riesel, G. Drying out electric mine loco- motives	Hooker, A. B. Davy safety lamp 134 Hutchings, N. Mine supplies 952	Kose, J. Drawing lots for working places, 181
right, G. Equipment when electric power fails		—Prevention mine explosions
—Power plant problem 890	ILLSLEY, L. C. Concentric all-rubber covered cables 280	—Hook for opening car door*694
roadt, P. Dynamic braking electric mine locomotives324		CCHAFFER W Advantages purchased
cars	JAMES, W. H. Electric cap lamp 19	SCHAFFER. W. Advantages purchased power 818 Schaphorst, W. F. Keep belt efficiencies
-Track device regulates traffic*179	Johnson, R. G. Design and sinking of	Schaphorst, W. F. Keep belt efficiencies
Sinking Spelterville shafts	Jones, C. L. Carbon dioxide fights Bitner	high ** Rect of conductors ** 859 Shaner, B. K. Heating of conductors ** 932 Sparks, R. W. Group insurance
Lynch mine	Jones, O. H. Drawing mine timbers 440	Strain, W. Machine mining in steep
Ejected cement	——Flooding of slope mine 672	pitches 147
with rock partings 709	KENNETT, O. Retimbering shaft bottom. 183	TESCHER, S. Two fans at Royal mine *845
Sutcher, I. A. What's trouble with mine power house?		
Butler, M. C. Normal vs. reverse faults *519	Kenworthy, O. E. Revolving field in in- duction motor	Thomas, E. P. Dewatering wet hole in blasting
	Kersten J Washer removes refuse in	Thomas, R. Entry of air to safety lamps. 146 Thompson, J. Bituminous law (Pa.)
CALDER, G. Authority mine inspector., 326	Krape, R. D. Electric braking on mine locomotives	ventilation
Chadbourne, H. W. Mine hoist control		——Responsibility for mine explosions 566 ——Retrograde mining examinations 784
equipment	LAMIE, R. D. Low temperature distilla-	Retrograde mining examinations 784 Tolmachoff, I. Coal of Soochan 550 Traber, C. K. Aerial tramway 917 Truscott, W. E. Give fireboss best possible
written warranties	Lawall, C. E. Faults of erosion vs. dis-	Truscott. W. E. Give fireboss best possible
Clevenberg, G. F. Are valleys accompanied	Lee, C. Standardization underground trans-	Tryon, F. G. Storage
by dips? 14	mission 923	particles from associated water 277
Cooley, H. B. Gallup-American Coal Co *165, *237, *387, *427	Libioz, G. F. Entering abandoned mines. 519 Lightburn, R. W. Safeguarding slope mine, 439	
Cornet, F. C. Obeying spirit of law 218		WADE, E. S. Extinguished carbide light
creveling, C. J. Longest mine-drainage	Posting in mines	Walker, R. W. Steel mine track ties 405
tunnel 111	Luxton, J. R. Sandpaper for cleaning com-	Walls. J. Post timbering
AVIDSON, E. W. Mine Inspectors Inst.	mutators	Working three contiguous seams *826
of Amer	——Downthrow or Upthrow, which?	Walsh, T. A. Group insurance
Denholm, A. Working double seam coal 68 De Yoe, D. H. Safety in electric welding	Peril in use of carbide lamp 899	Wood, F. R. Sentiment for fuel oil passing, 93; Woody, G. V. Centrifugal vs. recipro-
and cutting 15 Dickinson, W. Breaking of roof 254 Dickson, J. Working twin coal seams. 364 Downing, T. F., Jr. Where to build min-	MacWILLIAMS, J. F. Electric mine	cating pump
Dickson, J. Working twin coal seams*364	haulage	——Anthracite report117, 151 (e) 45
ing towns	McKenney W. F. Storage	——President Harding's death, effect 22: ——McMenimen's remarks on labor 32:
Extension and removal of rails*898	McNeil, J. C. Machine bookkeeping at mine	——Comment final report Coal Comm 473 ——Operators averse to Govt. experiments. 523
Destination of Destination	McNeil, J. Developing two seams on steep	——Coal legislation in next Congress 56'
DWARDS, G. Posting face of coal driving rooms	Magdalena, J. Flooding of slope mine 291	——Non-union producers in strong position, 60: ——I. C. C. ruling on private cars 67:
Mine supplies re working conditions. 363Mine safety bulletins 404		— Need of dictator
—Cooperating with mine inspector 935	Mason, F. H. Is coal of Vancouver ex-	844, 888, 922, 95
Preventing gas explosions 968 Edwards, J. H. Records mechanical and	Mason, L. G. Distribution transformers •623	Federal control
Edwards, J. H. Records mechanical and electrical equipment*586 Emerson, G. H. Maintaining trolley wheels, 860	Martin, J. D. Tracks, mine, standardiza- tion *351 Mason, F. H. Is coal of Vancouver ex- hausted *777 Mason, L. G. Distribution transformers. *623 Maxwell, M. A. Vertical shaft hoisting equipment *581 Means. C. M. Inherent disadvantages at	——Compulsory cost returns 82: ——Failure Pinchot Governors' meeting 85:
which which which which was	Means, C. M. Inherent disadvantages at power plant	
FOKES, R. Paralleling new transformer *517	—Reports by engineers	Oddie to base legislation on Comm. re-
Fraser. T. Resistance to flow of air*821	Mottisnaw, S. K. wakesiah explosion 289	port 96
Freeman, H. B. Concentric all-rubber	NEAR, N. G. Crumb coke 182	YOUNG, D. Making mines safer 1
	41	•

